



Identiv Connected Physical Access Manager (ICPAM) version 2.1.0 Release Notes

The Identiv Connected Physical Access Manager (ICPAM) v2.1.0(0.3.5) software integrates with the Identiv EM-100 Controller. Together with the Identiv TouchSecure Reader line, the ICPAM solution offers a complete premises access management system combining strong authentication with Identiv secure credentials at the door. The system includes support for legacy systems, enabling a mixed-environment of both EM-100 Controllers and Cisco Physical Access Gateways (CIAC-GW-K9).

This document contains important information about the ICPAM software version 2.1.0, including an overview of release scope, policy and procedures, minimum system requirements, reference documentation, exclusions and an explanation of resolved issues and caveats.

NOTE: Upgrade to ICPAM v2.1.0 is mandatory for customers with EM-100 Controllers, or a mixed environment consisting of EM-100 Controllers and Cisco Physical Access Gateways.

Table of Contents

- Scope of Release - Features
- Upgrade Paths
- Policies and Procedures
 - Minimum System Requirements
 - Implementation Notes
 - Exclusions
- Obtaining Software, Documentation and Related Information
 - Software Images and Other Tools
 - Related Documentation
 - Support and Service Requests
- Resolved Issues and Caveats
 - Caveats
 - Resolved Issues

Scope of Release - Features

Controller Support

ICPAM 2.1.0 supports management of Identiv EM-100 Controllers, while simultaneously providing continued support for Cisco Physical Access Gateways.

Upgrades

In-place upgrades from existing customer deployments of CPAM 1.5.x are supported. No need to make configuration changes or replace current UCS, gateway, or desktop hardware, and operating systems that meet recommended minimum system requirements. Cisco Physical Access Gateways must be upgraded to v1.5.3 firmware prior to upgrade.

Simplified Licensing

The ICPAM solution enables customers to install software with ease. No need to purchase the ICPAM software as a separate product. In addition, license counts have been removed and the optional modules of badge designer and web services API have been included.

Continued Integration

ICPAM integrates with Cisco Video Surveillance Manager (VSM) to provide total access, single point of security, any distance from the door.

Workflow Changes

Virtual Credential Templates have been introduced to enable support for controller-type specific credential templates. A Virtual Credential Template references one type-specific credential template per type of controller.

The filter option in the various list dialogues is disabled by default. If needed, this option can be re-enabled via User Profiles.

Upgrade Paths

Upgrade is mandatory for customers deploying EM-100 Controllers, or an environment consisting of EM-100 Controllers and Cisco Physical Access Gateways.

The following upgrade paths from CPAM to ICPAM 2.1.0 are supported:

- CPAM 1.5.0 to ICPAM 2.1.0(0.3.5)
- CPAM 1.5.1 to ICPAM 2.1.0(0.3.5)
- CPAM 1.5.2 to ICPAM 2.1.0(0.3.5)
- CPAM 1.5.3 to ICPAM 2.1.0(0.3.5)

Note:

System configuration checks are performed as part of the upgrade process. If a conflict is detected, the upgrade process will gracefully exit, leaving the system in its original state. The following conditions will prevent upgrade:

- CPAM version earlier than v1.5.0
- A VSM 6.x driver installed present

Customers using older CPAM versions (1.4.x and below) will need to first upgrade to 1.5.3 then to 2.1.0. Reference Cisco 1.5.3 release notes for further upgrade details.

Additional upgrade instructions for ICPAM can be found in the ICPAM installation guide accessible at: <http://www.identiv.com/support-icpam>

For reference the Cisco v1.5.3 release notes can be found at http://www.cisco.com/c/en/us/td/docs/security/physical_security/access_control/release_notes/1_5_3/cpac_rm_1_5_3final.html

Cisco CPAM install and upgrade document can be found with the Cisco Physical Access Manager Documentation at: http://www.cisco.com/en/US/products/ps9688/tsd_products_support_series_home.html

Identiv CPAM 2.1.0 supports Cisco Physical Access Gateways with the 1.5.3 version of firmware. Future iterations of ICPAM will no longer implicitly require Gateway firmware to be upgraded. See the [Cisco Physical Access Gateway User Guide](#) for instructions to upgrade older firmware versions to 1.5.3.

Policies and Procedures

This section provides general policies and procedures regarding installation and service-related issues for this release.

Minimum System Requirements

Requirement	Description
Workstation software requirements	<ul style="list-style-type: none"> Windows 7 or Windows 8 and Internet explorer versions 8-11. 32 bit Java runtime environment 1.6 (release 27) or 1.7 (release 79) for both installation and normal use. User account with administrative privileges.
Workstation hardware requirements	<ul style="list-style-type: none"> Modern Intel or AMD multicore IV processor. 4GB RAM or more. 250MB hard disk space available for the application, and an additional 200MB or more disk space for data storage.
Server hardware requirements	<ul style="list-style-type: none"> ICPAM server includes at least 16GB of RAM memory, four virtual processors, and sufficient hard drive capacity to accommodate the database and software (450GB)
ICPAM appliance software requirements	<ul style="list-style-type: none"> ICPAM Release 2.1.0
Physical access controllers and/or controller modules	<ul style="list-style-type: none"> Identiv EM-100 Controllers: Firmware Release 3.5.1 is required on all Identiv EM-100 controllers. The EM-100 will ship with FW version 3.5.1 from the factory. Cisco Physical Access Gateways: Firmware Release 1.5.3 is required on all physical access gateway modules. Some older physical access gateways may need an upgrade. To upgrade older firmware versions on physical access gateways to 1.5.3, see the Cisco Physical Access Gateway User Guide for instructions.

Implementation Notes

- Conditional Support for JRE 1.7 (release 79):
The updated security settings in JRE 1.7 (release 79) may interfere with the normal functioning of the ICPAM client. The security settings in the Java control panel settings must be set to Medium: [Control panel -> Java (32-bit) -> Select **Medium** and select **OK**] to allow the installation of the ICPAM client. Users may face issues while performing functions with third party devices like badge printers or image capture devices. In such situations, Java runtime environment 1.6 (release 45) is recommended.
- VMware:
An ICPAM server runs as a Linux Virtual Appliance on VMware vSphere 5.x or 6.x (Other virtualization products, such as Oracle VirtualBox, Microsoft Hyper-V, Xen, etc. are not supported.)
- Encryption:
EM-100 AES encryption is unsupported in this release and must be disabled in both the controller and ICPAM configuration.

Steps to disable:
Configure the EM-100 controller by using a browser to logon to the controller. In Advanced Settings, ensure the “Encrypt Host Communication” checkbox is not checked (not encrypt).

When adding the EM-100 controller to ICPAM in the hardware tree, ensure the “Use encryption” checkbox is unchecked in the “Configuration” tab.
- APB (Anti-Passback) is not supported for EM-100 Doors
- Two Door policies is not supported for EM-100 Doors
- Doors are no longer added through the Locations/Doors module, only through the Logical Driver. Once doors are created, go to Locations/Doors and drag the unassigned doors into the relevant location, or alternatively, set the locations by editing the doors.

Exclusions

- VSM 6.x is not supported with ICPAM v2.1.0; VSM 7.x will continue to be supported. Existing CPAM 1.5.x installations integrated with VSM 6.x will need to migrate to VSM 7.x before upgrading to ICPAM.
- JRE 1.8 is unsupported and is known to cause issues with Cisco VSM video playback in the ICPAM client and with the ICPAM map display.

Obtaining Software, Documentation and Related Information

Software Images and Other Tools

To access the self-service portal and obtain software, documents, and tools, do the following:

- Download ICPAM software:
Go to the following URL: <http://www.identiv.com/support-icpam>
Click the **Registration and Downloads** tab.
Register user to enable access to software download link.
- Download Credential Template VFF files:
Go to the following URL: <http://www.identiv.com/icpam-credential-templates>
Select the applicable template zip files for your credential format.
Click the link to download.
- ICPAM v2.1.0 Implementation Guide and ICPAM v2.1.0 Installation Guide:
Go to the following URL: <http://www.identiv.com/support-icpam>
Click the ICPAM documents tab and select the guide.

Related Documentation

To obtain data sheets and other important information go to:

Identiv Connected Physical Access Manager documentation:

- For general product information: <http://www.identiv.com/icpam>
- For links to access Technical Data Sheets and product information: <http://www.identiv.com/support-icpam>

Cisco CPAM Physical Access Gateway documentation:

- http://www.cisco.com/en/US/products/ps9687/tsd_products_support_series_home.html

Support and Service Requests

To contact ICPAM support, go to the following link and submit your request via web or contact us: <http://www.identiv.com/support-icpam>

Resolved Issues and Caveats

Caveats

Resolutions for these issues are currently being investigated and will be scheduled for a future release unless specified.

Additional descriptions, status, or workaround information can be found using the [Bug Search Tool](#).

Identifier	Title
CSCuv50557	Advanced Gateway options not seen in single screen badge wizard.
CSCuv71842	EM-100 driver needs restart to apply controller configuration change.
CSCuw55423	Error while executing "createTimeEntry" in WS API.
CSCuw61388	Blank schedule is created when we try to create schedule through API.
CSCuw98089	CSV import wizard has no support for new badge fields (advanced).
CSCuo83272	CPAM MySQL bin files occupying the entire space when Stand-By is absent.
CSCul35210	CPAM Client does not respond when viewing Sanity Report, "Badges - Added (or changed) since the most recent download".
CSCul62691	CreateTEC API allows pushing to parallel location objects for a profileUser.
ICPAM-129	After upgrade the filter option is not displayed. Work around: After upgrade, go to Profiles and enable filter option for each required module.
ICPAM-139	Unable to edit an existing badge template which was created before upgrade. Work around: Create a new template after upgrade.
ICPAM-174	Global IO Automation driver fails for "Send to Windows Shared Directory" notification.

Resolved Issues

The following issue resolutions are included with ICPAM version 2.1.0(0.3.5).

Identifier	Title
CSCul97024	Default columns values are not set for default reports.
CSCua70764	CPAM Client throws Fatal error when opening modules.
CSCuw33642	Commands issued through Maps for Cisco Doors fails.
CSCuw33778	Issue in adding commands for EM-100 Doors in Map Editor.
CSCuw98128	Badges - Not able to create a badge using badge template.